

ECS Configuration Change Request

Page 1 of

Page(s)

1. Originator Sarah Lewallen	2. Log Date: 1/21/02	3. CCR #: 02-0044	4. Rev: -	5. Tel: 301-925-0865	6. Rm #: 2117B	7. Dept. SED
8. CCR Title: Install a 68 GB drive into all Dell Rimage Hosts						
9. Originator Signature/Date /s/ Sarah Lewallen 1/21/02			10. Class II	11. Type: CCR	12. Need Date: 2/28/02	
13. Office Manager Signature/Date /s/ Valecia Maclin 1/21/02			14. Category of Change: Update ECS Baseline Doc.		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted: None			17. Schedule Impact: none		18. CI(s) Affected: DISTHW	
19. Release Affected by this Change: 6A, 6B		20. Date due to Customer: 2/28/02		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input checked="" type="checkbox"/> Other: PDS						
23. Problem: (use additional Sheets if necessary) Need additional space for DVD production on the Rimage Host						
24. Proposed Solution: (use additional sheets if necessary) Install a new hard drive into the third internal bay. Install a new SCSI adapter and connect the drive. Configure per PDS instructions.						
25. Alternate Solution: (use additional sheets if necessary) Leave it alone						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Less DVD staging area available						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input checked="" type="checkbox"/> EDF <input checked="" type="checkbox"/> PVC <input checked="" type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input checked="" type="checkbox"/> LaRC <input checked="" type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. EDF/SCDV CCB Chair (Sign/Date): Byron Peters, Kevin Lange 1/23/02			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
33. M&O CCB Chair (Sign/Date): Gary Gavigan /s/ 1/22/02			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS			

ADDITIONAL SHEET

CCR #: 02-0044 **Rev:** - **Originator:** Sarah Lewallen

Telephone: 301-925-0865 **Office:** 2117B

Title of Change: Install a 68 GB drive into all Dell Rimage Hosts

Instructions for installation:

Remove the front cover of the Dell PC.

Unscrew the 3 screws along the right edge.

Slide the cover forward slightly then lift off.

Install SCSI card into free slot

Connect the drive to the LVD port of the card. This port is the one closest to the back plane (see page 8 of the adaptec installation guide, step 2)

Install the drive in the empty slot below the DVD ROM drive.

Connect to the end connector of the braided cable (see page 8 of the adaptec installation guide, step 3)

EZ SCSI is already installed and should not need to be installed again.